




Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
 Rendelhető alkatrészek / Запасні частини / Reservní deloví / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



XX = AA, GN, ...

Pos.	Part No.		
1	A 861 521 XX	7	A 964 520 NU
2	A 861 417 XX	8	A 962 370 NU
3	A 861 397 NU		B 960 364 NU
4	A 961 855 NU	9	A 961 172 NU
5	B 961 383 XX	10	B 960 900 XX
6	A 861 227 XX	11	A 961 230 XX

A7049



P	T	°C	4	3	2	1	0
			°C	°C	°C	°C	°C
0,3 MPa 3 bar	50°C	15°C	27	33	41	48	50
	65°C	15°C	33	42	53	63	65
	85°C	15°C	41	53	68	83	85




Ideal Standard

CONNECT AIR


A 7046 .. A 7047 .. A 7048 .. A 7049 ..

0321 / A 868 880
 Made in Germany


A 7049 ..





A 7048 ..



A 7046



A 7047



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium

www.idealstandardinternational.com



